## PARTS DEPARTMENT BULLETIN

**DATE:** June 25, 2009 **BULLETIN NUMBER:** 2009-3

**SUBJECT:** SEA WATER PUMP #301357

**DETAIL:** THREE CHANGES HAVE TAKEN PLACE WITH SEA WATER PUMP #301357.

- 1. THE COVER PLATE IS NO LONGER A CASTING. IT IS NOW A STAMPED BRONZE PLATE.
- 2. THE CAM IN THE PUMP IS NO LONGER A SEPARATE COMPONENT. IT IS NOW MACHINED AS PART OF THE PUMP HOUSING.
- 3. THE COVER PLATE IS NOW SEALED WITH THE USE OF AN "O" RING AND THE PUMP HOUSING NOW HAS A MACHINED GROOVE IN IT TO RETAIN THE "O" RING.

THE "O" RING PN#201080 WILL BE ADDED TO THE IMPELLER KIT #200209 AND THE PUMP REPAIR KIT #200212.

INSERT A COPY OF THIS PARTS BULLETIN INTO EACH OF THE UNIVERSAL PARTS LISTS THAT ILLUSTRATE THIS SEA WATER PUMP.

